

Table ENG-5. - Sanitary Facilities

Charlotte County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
AbB:					
Abell	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage Slope	0.50 0.32
Worsham	5	Not Rated		Not Rated	
Ad:					
Alluvial Land	80	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	0.50
AfA:					
Altavista	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00	Seepage	0.50
AfB:					
Altavista	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00	Seepage	0.50
AfC2:					
Altavista	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00	Slope Seepage	1.00 0.50
AgB2:					
Appling	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage Slope	0.50 0.32
Worsham	3	Not Rated		Not Rated	

AgD2:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
AgD2:					
Appling	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
AgE2:					
Appling	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
AIB2:					
Appling	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Worsham	3	Not Rated		Not Rated	
AIC:					
Appling	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
AID2:					
Appling	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
AIE2:					
Appling	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
AmB2:					
Appling	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Worsham	3	Not Rated		Not Rated	
AmD2:					
Appling	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
ApC3:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
ApC3:					
Appling	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
ApE3:					
Appling	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
AuA:					
Augusta	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00	Seepage	0.50
Roanoke	5	Not Rated		Not Rated	
AuB:					
Augusta	85	Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00	Seepage	0.50
		Flooding	0.40	Flooding	0.40
Bn:					
Buncombe	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
Bt:					
Buncombe	45	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Filtering capacity	1.00	Seepage	1.00
Toccoa	40	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage	1.00
				Depth to saturated zone	0.92
Frequently flooded	5	Not Rated		Not Rated	
CcB2:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CcD2:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CcE2:					
Cecil	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CeB2:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
CeD2:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CeE2:					
Cecil	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CfB2:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
CfD2:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CfE2:					
Cecil	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CIB3:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32

CID3:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CID3:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CIE3:					
Cecil	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CmB3:					
Cecil	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
CmD3:					
Cecil	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Cn:					
Chewacla	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Filtering capacity	1.00	Seepage	1.00
Wehadkee	5	Not Rated		Not Rated	
CoB:					
Colfax	85	Very limited		Very limited	
		Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to saturated zone	1.00	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
Worsham	5	Not Rated		Not Rated	
Cr:					
Congaree	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.50	Seepage	0.50
Chewacla	5	Not Rated		Not Rated	

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
CsB2:					
Creedmoor	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.32
		Depth to saturated zone	1.00	Depth to saturated zone	<0.01
				Seepage	<0.01
CsC2:					
Creedmoor	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	<0.01
				Seepage	<0.01
Worsham	3	Not Rated		Not Rated	
CuB2:					
Cullen	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
CuD2:					
Cullen	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
CuE2:					
Cullen	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
CvB3:					
Cullen	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
CvD3:					
Cullen	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
EnB2:					
Enon	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Depth to hard bedrock	0.96
		Depth to bedrock	0.99	Slope	0.32
				Seepage	<0.01
EnC2:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
EnC2:					
Enon	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to bedrock	0.99	Depth to hard bedrock	0.96
				Seepage	<0.01
EoC3:					
Enon	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to bedrock	0.99	Depth to hard bedrock	0.96
				Seepage	<0.01
GeB2:					
Georgeville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
GeD2:					
Georgeville	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Worsham	3	Not Rated		Not Rated	
GeE2:					
Georgeville	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
GgB3:					
Georgeville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
GgD3:					
Georgeville	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
Worsham	3	Not Rated		Not Rated	
GoC:					
Goldston	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
				Seepage	1.00
				Slope	1.00

GoD:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
GoD:					
Goldston	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.84	Slope	1.00
				Seepage	1.00
GoF:					
Goldston	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
GrB2:					
Grover	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
GrD2:					
Grover	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
GuE:					
Gullied land	50	Not Rated		Not Rated	
Cecil					
	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
HeB:					
Helena	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.32
		Depth to saturated zone	1.00		
HeC2:					
Helena	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00		
HfB2:					
Helena	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.32
		Depth to saturated zone	1.00		

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
HfC2:					
Helena	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00		
HnB2:					
Herndon	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
HnD2:					
Herndon	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
HrB3:					
Herndon	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
Worsham	3	Not Rated		Not Rated	
HrD3:					
Herndon	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
IrB:					
Iredell	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Depth to hard bedrock	0.61
		Depth to saturated zone	1.00	Slope	0.32
		Depth to bedrock	0.86		
IrB2:					
Iredell	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Depth to hard bedrock	0.61
		Depth to saturated zone	1.00	Slope	0.32
		Depth to bedrock	0.86		
IrC2:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
IrC2:					
Iredell	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to hard bedrock	0.61
		Depth to bedrock	0.86		
LoD:					
Louisa	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	0.37	Seepage	1.00
				Slope	1.00
LoF:					
Louisa	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
LsE3:					
Louisa	70	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Louisburg	20	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00
LuC:					
Louisburg	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Seepage	1.00
				Slope	1.00
LuD:					
Louisburg	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Filtering capacity	1.00	Slope	1.00
		Slope	0.84	Seepage	1.00
LuF:					
Louisburg	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Filtering capacity	1.00	Seepage	1.00

MaB2:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MaB2:					
Madison	85	Somewhat limited		Somewhat limited	
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
				Depth to hard bedrock	0.26
MaD2:					
Madison	85	Somewhat limited		Very limited	
		Depth to bedrock	0.70	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to hard bedrock	0.26
McB3:					
Madison	85	Somewhat limited		Somewhat limited	
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
				Depth to hard bedrock	0.26
McD3:					
Madison	85	Somewhat limited		Very limited	
		Depth to bedrock	0.70	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to hard bedrock	0.26
MdE2:					
Madison	50	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Depth to hard bedrock	0.26
Grover	30	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MeB2:					
Masada	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
MeD2:					
Masada	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
MeE:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MeE:					
Masada	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
MfB2:					
Mayodan	85	Somewhat limited		Somewhat limited	
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Slope	0.32
				Depth to hard bedrock	0.26
MfD2:					
Mayodan	85	Somewhat limited		Very limited	
		Depth to bedrock	0.70	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Slope	0.37	Depth to hard bedrock	0.26
MkB2:					
Mecklenburg	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Seepage	0.50
		Depth to bedrock	0.70	Slope	0.32
				Depth to hard bedrock	0.26
MkC2:					
Mecklenburg	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to bedrock	0.70	Seepage	0.50
		Slope	0.04	Depth to hard bedrock	0.26
MIB:					
Mecklenburg variant	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
MIC:					
Mecklenburg variant	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Restricted permeability	0.50	Slope	1.00
				Seepage	0.50
MIE:					
Mecklenburg variant	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
MIE3:					
Mecklenburg variant	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
OrB:					
Orange	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Depth to soft bedrock	0.61
		Depth to saturated zone	1.00	Slope	0.32
		Depth to bedrock	0.86		
Worsham	3	Not Rated		Not Rated	
OrB2:					
Orange	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Depth to soft bedrock	0.61
		Depth to saturated zone	1.00	Slope	0.32
		Depth to bedrock	0.86		
Worsham	3	Not Rated		Not Rated	
OrC2:					
Orange	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to saturated zone	1.00	Depth to soft bedrock	0.61
		Depth to bedrock	0.86		
Worsham	3	Not Rated		Not Rated	
PaB2:					
Pacolet	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage	0.50
		Depth to bedrock	0.36	Slope	0.32
				Depth to hard bedrock	0.01
PaD2:					
Pacolet	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
		Depth to bedrock	0.36	Depth to hard bedrock	0.01

PaE2:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
PaE2:					
Pacolet	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
		Depth to bedrock	0.36	Depth to hard bedrock	0.01
PcC3:					
Pacolet	85	Somewhat limited		Very limited	
		Depth to bedrock	0.70	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
				Depth to hard bedrock	0.26
PcD3:					
Pacolet	85	Somewhat limited		Very limited	
		Slope	0.84	Slope	1.00
		Depth to bedrock	0.70	Seepage	0.50
		Restricted permeability	0.50	Depth to hard bedrock	0.26
PkC:					
Pinkston	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
				Seepage	1.00
				Slope	1.00
PKE:					
Pinkston	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to soft bedrock	1.00
		Slope	1.00	Slope	1.00
				Seepage	1.00
Ro:					
Roanoke	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Seepage	0.50
SrB:					
Starr	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Seepage	1.00
		Flooding	0.40	Flooding	0.40
				Slope	0.32
StB:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
StB:					
State	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Restricted permeability	0.50	Seepage Slope	1.00 0.32
Wet spots	3	Not Rated		Not Rated	
To:					
Toccoa	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Seepage Depth to saturated zone	1.00 0.92
TuB2:					
Turbeville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage Slope	0.50 0.32
TuD2:					
Turbeville	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
TuF2:					
Turbeville	85	Very limited		Very limited	
		Slope	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	0.50
TvB3:					
Turbeville	85	Somewhat limited		Somewhat limited	
		Restricted permeability	0.50	Seepage Slope	0.50 0.32
TvD3:					
Turbeville	85	Somewhat limited		Very limited	
		Restricted permeability	0.50	Slope	1.00
		Slope	0.37	Seepage	0.50
VaB2:					
Vance	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.32
		Depth to bedrock	0.70	Depth to hard bedrock	0.26
Worsham	3	Not Rated		Not Rated	

VaD2:

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
VaD2:					
Vance	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to bedrock	0.70	Depth to hard bedrock	0.26
		Slope	0.37		
VcB2:					
Vance	85	Very limited		Somewhat limited	
		Restricted permeability	1.00	Slope	0.32
		Depth to bedrock	0.70	Depth to hard bedrock	0.26
Worsham	3	Not Rated		Not Rated	
VcC2:					
Vance	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Depth to bedrock	0.70	Depth to hard bedrock	0.26
VcD2:					
Vance	85	Very limited		Very limited	
		Restricted permeability	1.00	Slope	1.00
		Slope	0.84	Depth to hard bedrock	0.26
		Depth to bedrock	0.70		
WdB2:					
Wedowee	85	Somewhat limited		Somewhat limited	
		Depth to bedrock	0.86	Depth to hard bedrock	0.61
		Restricted permeability	0.50	Seepage	0.50
				Slope	0.32
WdD2:					
Wedowee	85	Somewhat limited		Very limited	
		Depth to bedrock	0.86	Slope	1.00
		Restricted permeability	0.50	Depth to hard bedrock	0.61
		Slope	0.37	Seepage	0.50
We:					
Wehadkee	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.82	Seepage	0.50
Wh:					

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
Wh:					
Wehadkee	85	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.82	Seepage	0.50
Roanoke	5	Not Rated		Not Rated	
Wet spots	3	Not Rated		Not Rated	
Wk:					
Wehadkee	45	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Restricted permeability	0.82	Seepage	0.50
Chewacla	40	Very limited		Very limited	
		Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Filtering capacity	1.00	Seepage	1.00
WIB:					
Wickham	85	Very limited		Very limited	
		Filtering capacity	1.00	Seepage	1.00
		Restricted permeability	0.50	Slope	0.32
WIC2:					
Wickham	85	Very limited		Very limited	
		Filtering capacity	1.00	Slope	1.00
		Restricted permeability	0.50	Seepage	1.00
WmB:					
Wilkes	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
				Depth to soft bedrock	1.00
				Slope	0.32
WmD:					
Wilkes	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	0.37	Depth to soft bedrock	1.00
				Slope	1.00

Table ENG-5. - Sanitary Facilities - Continued

Charlotte County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Septic Tank Absorption Fields		Sewage Lagoons	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
WmF:					
Wilkes	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Depth to soft bedrock	1.00
				Slope	1.00
WnC3:					
Wilkes	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
				Depth to soft bedrock	1.00
				Slope	1.00
WnF3:					
Wilkes	85	Very limited		Very limited	
		Depth to bedrock	1.00	Depth to hard bedrock	1.00
		Slope	1.00	Depth to soft bedrock	1.00
				Slope	1.00
Wo:					
Worsham	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00		
Wr:					
Worsham variant	85	Very limited		Very limited	
		Restricted permeability	1.00	Depth to cemented pan	1.00
		Depth to cemented pan	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00		